

2  
↓

# Side Mount Case IH MXM 175,190


1

PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	2	20-1800	Saddle Conv.
2	2	20-1011	300 Saddle
3	1	30-1903	Step bottom Bracket
4	1	30-1902	Step Handle
5	1	20-1023L	6' 12deg Offset Tube LH
6	1	20-1412L	MXM 190 Side Plate LH
7	1	20-1412R	MXM 190 Side Plate RH
8	1	20-1023R	6' 12deg Offset Tube RH
9	1	20-1208	MXM 190 Undertruss 5 x 7







Bolt List		
QTY	Description	Placement
8	20 mm x 70 mm Bolts	Side Plate to Tractor
8	20 mm Harden Flatwashers	
8	20 mm Nuts	
24	3/4 x 2 1/2 Bolts	Side Plates to Undertruss
20	3/4 x 2 1/2 Bolts	Side plate to Tube
4	3/4 x 7 x 9 U Bolts	Conv to Tube
12	3/4 x 2 1/2 Bolts	Saddle to Conv
64	3/4 in Lock Washers	
64	3/4 in Nuts	
4	Nylon Straps	Tank to Saddle

**Price List**  
**\$5390.00**

Limitations may apply. Please consult API Sales at 800-288-1117.



Front



300 ID: CS-MXM-0207-SMS-300R

2



1

B

B

A

A